

FOR CENTRAL OFFICE USE ONLY

**ESTABLISHMENT NUMBER** 

Establishment Name / /						Name ,				
Ceder stone Lodge						Bill Hendrix				
Physical Address 15233 Czcs Stone					City Eminence				2108466	
Mailing Address					City				Zip. 5466	
POB 338						rinerco				
County This inspection is a(n)										
Rooms Inspected: Water Supply Wastewater										
							□ Public			
				ater sample taken □ Yes □ No Regulated by: □ DHSS					DNR	
					g Pools/Spas (check all that apply) ol  Outdoor pool  Spa  Pool larger than 200				O square foot	
Please check if the following										
local ordinances apply	New Loughi	EStat	manini							
☐ Fire Safety ☐ Electrical Wiring								No N/A		
□ Plumbing	Fire alarm system installed			Building Certified to National Standards or Occup Permit						
Swimming Pools/Spas	Sprinkler eyetem inetalled			□Y					No N/A	
☐ Fuel Burning Appliances  Based on an inspection this day, the iter										
Based on an inspection this day, the items marked "Out" below identify noncompliance in operations or facilities which must be corrected prior to issuance or renewal of your lodging license. Failure to comply with any time limits for corrections specified in this notice may result in revocation of your lodging license										
and/or prosecution. Owners may request a hearing before the Department Director upon filing a written request within ten days after receipt of this notice.										
(RSMo 315.005-065, 19 CSR 20-3.050) In=In Compliance Out=Not In Compliance, explain on additional page(s) NO=Not Observed N/A=Not Applicable										
Section A & B: Water Supply & Wast		Out	NO		Section E: Fire		ODSCIVED IN	In	Out NO N/A	
1. Approved source, construction and or	peration				1. Textiles, hang	<u> </u>				
2. Complies with water quality standards							cted, and location	1/		
Chlorinator maintained and operated properly     Wastewater operation and maintenance				Vertical openings fire-rated, self-closing     Doors, self-closing and fire-rated				gradent and a second		
Section C: Sanitation/Housekeeping		The same		Smoke detectors hardwired, installed, good repair						
1. Walls, floors and ceilings in good repair				6. Evacuation route and plan, installed, available						
Housekeeping practices and furnishings				7. Stairs and ramps, maintained, storage						
3. Towels and bed linens clean				Means of egress, number, maintained     Handrails and balconies maintained and appropriate						
Mattresses and box springs clean     Pest control procedures					ection F: Swimming Pools/Spas					
6. Ice machines, scoops, liners clean & protected				Fence, gate adequate, proper closure mechanism						
7. Garbage storage and disposal					2. Boundary line					
8. Premises maintained, plant growth controlled					3. Deck is clean	and in good re	pair			
Food Inspection conducted according to 19CSR20-1.025  9. Food, equipment and single service/use							equate, good rep			
10. Food protected from contamination					Pool clarity, pH, disinfectant, & temp. maintained     Steps, ladders, and handrails installed, good repair					
11. Facilities to wash, rinse and sanitize				7. Adequate ver						
12. Handwashing facilities/hygienic practices							tection & distance	9		
Section D: Life Safety			No.		9. Records mair		ns posted			
Combustible/toxic items usage and st     Building maintained to assure safe co					10. First aid kit a					
Building maintained to assure safe conditions     CO detectors hardwired, installed, good repair					Section G: Plu					
4. GFCI, outlets & switches installed, good repair					1. Equipment ac					
5. Exit signs installed, good repair					2. Ventilation ac					
Emergency lighting installed, good repair     Electric panel protected, labeled, good repair					3. T & P relief valves adequate, good repair 4. Relief valve discharge pipes installed, adequate					
Required Annual Third Party Inspecti		5/1	100		5. Backflow, air					
Fire Alarm System					Section H: Hea	ating & Coolin	g			
2. Sprinkler System							ance/space heate	r		
<ol> <li>Local Fire and Building Codes/Ordina</li> <li>Current Boiler/Pressure Vessels MDP</li> </ol>					2. Fire resistant	room or sprink	ier nead			
Certification					3. Location of he	eating/cooling u	units			
5. Backflow Device(s) Test					4. Ventilation of	appliances and	d utility rooms			
6. Liquid Propane Leak Test	1 0101,	1	1		5. Operation and		equate	TELEBUIC	IF.	
INSPECTED BY (PRINT NAME and SIGN)  LEVIN DUICE TELEPHONE  1773 Texts Cottacth D. TELEPHONE  1773 Texts Cottacth D. 177/807/413/										
LICENSING YEAR DATE INSPECTED FOLLOW UP DATE									P DATE	
20 120 25 APPROVED X YES   NO 7/3/24							A	A		
RECEIVED BY (PRINT NAME AND TITLE and SIGN)  PAGE 1 OF									1	
TAGE TOT _										
X	2		16	ONa	nel					
MO 580-0883 (6-16) Distribution: White/Owner Canary/Central Office Pink/Local Office									E9.02	